

Oil Field Environmental Incident Summary

Incident: 20160413164520 **Date/Time of Notice:** 04/13/2016 16:45

Responsible Party: MAXXON Trucking

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: VIXEN FEDERAL 1 SLH

Field Name: BIG BEND

Well File #: 29435

Date Incident: 4/13/2016

Time Incident: 13:30

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 91

Sec: 18

Qtr:

Location Description:

Submitted By: Ray Gorka

Received By:

Contact Person: Brian Smith
131 104 S Ave S W,
Killdeer, ND 58640

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1180 Feet

Distance Nearest Water Well: 1180 Feet

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.9	Barrels	1.9	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

Contained on pad.

Potential Environmental Impacts:

None.

Action Taken or Planned:

STAY OUT OF CAB WHEN LOADING OIL.

Wastes Disposal Location: Clean Harbors.

Agencies Involved:

Updates

Date: 4/14/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on constructed well site according to the report. NDIC retains oversight.